




# GISON Pneumatic Tools

## GP-350 3/8" Low Speed Air Drill



### PARTS LIST

✳ : Consuming Part

Item No.	Part No.	Description	Qty.	Item No.	Part No.	Description	Qty.
1	350001	Screw	1	21	350021	Handle	1
2	350002	Chuck	1	22	350022	Switch Lever	1
3	350003	Bolt	1	23	350023	Air Inlet (18)	1
4	350004	Front Cap	1	24	350024	Screw	1
5	350005	O-Ring (P29.87 x 1.8)	1	25	350025	Speed Switch	1
6	350006	Ball Bearing (6001)	1	26	350026	O-Ring (P4 x 1.9)	1
7	350007	Pin (ø4 x 13)	2	27	350027	Pin (ø3 x 26)	1
8	350008	Gear Seat	1	28	350028	Spring	1
9	350009	Gear	2	29	350029	Iron Ball (ø1/8")	1
10	350010	Gear Ring	1	30	350030	Air Inlet (19)	1
11	350011	Ball Bearing (6201)	1	31	350031	Hook	1
12	350012	Ball Bearing (608)	1	32	350032	O-Ring (P8 x 1.5)	1
13	350013	Front Plate	1	33	350033	O-Ring (P11 x 2.4)	2
14	350014	Rotor	1	34	350034	Bushing	1
15	350015	Rotor Blade	6	35	350035	O-Ring (P3 x 1.9)	1
16	350016	Pin (ø2 x 6)	1	36	350036	Valve Rod	1
17	350017	Cylinder	1	37	350037	Spring	1
18	350018	Pin (ø2 x 18)	1	38	350038	O-Ring (P5 x 1.9)	1
19	350019	Rear Plate	1	39	350039	Reverse Valve	1
20	350020	Ball Bearing (626)	1	40	350040	Pin (ø2 x 20)	1