


吉生 **GISON**

GP-330 3/8" Low Speed Air Drill



PARTS LIST

✿ : Consuming Part

No.	Part No.	Description	Qty.	No.	Part No.	Description	Qty.
1	330001	Inlet Bushing	1	16	330016	Ball Bearing	2
✿ 2	330002	O-Ring	1	17	330017	Rear End Plate	1
4	330004	Exhaust Housing	1	18	330018	Ball	3
5	330005	Motor Housing	1	19	330019	Rotor	1
6	330006	Throttle Lever	1	✿ 20	330020	Rotor Blade	4
7	330007	Throttle Lever Pin	1	21	330021	Cylinder	1
8	330008	Valve	1	22	330022	Front End Plate	1
9	330009	Throttle Valve	1	23	330023	Idler Gear	3
✿ 10	330010	O-Ring	1	24	330024	Idler Gear Plate	1
11	330011	Spring	1	25	330025	Ball Bearing	2
12	330012	Air Regulator	1	27	330027	Ring Gear	1
✿ 13	330013	O-Ring	1	28	330028	Gear Cap	1
✿ 14	330014	O-Ring	1	40	840095	3/8" Chuck & Key	1
15	330015	Valve Screw	1	✿ 42	330042	O-Ring	2