


吉生 GISON

GP-950 Air Screw Driver



PARTS LIST

✳ : Consuming Part

Item No.	Part No.	Description	Qty.	Item No.	Part No.	Description	Qty.
1	950001	Housing	1	23	950023	Rear Plate	1
2	P011	Pin	1	24	SP014	Pin	2
✳ 3	OR023	O-Ring	1	25	950025	Cylinder	1
4	950004	Valve Bushing	1	✳ 26	950026	Rotor Blade	5
✳ 5	OR029	O-Ring	1	27	950027	Rotor	1
6	E2.5	Retaining Ring	1	28	950028	Front Plate	1
7	950007	Valve Bushing	1	29	B6000ZZ	Ball Bearing	2
✳ 8	OR024	O-Ring	1	30	950030	Lock Ring	2
9	950009	Reverse Valve	1	31	OR009	O-Ring	1
10	950010	Ball	2	32	950032	Cam	1
✳ 11	S015	Spring	1	33	950033	Hammer	2
12	950012	Regulator Valve	1	✳ 34	950034	Hammer Pin	2
13	950013	Reverse Lever	1	35	950035	Hammer Cage	1
14	SP013	Pin	1	36	950036	Anvil	1
15	950015	Trigger	1	37	950037	Flange Bushing	1
16	SP012	Pin	1	38	950038	Anvil Bushing	1
17	950017	Screen	2	39	950039	Hammer Casing	1
18	950018	Screen	1	✳ 40	950040	Ball Retaining	1
19	R14	Retaining Ring	1	✳ 41	S016	Spring	1
20	950020S	Hanger	1	✳ 42	950042	Washer	1
21	OR025	O-Ring	2	✳ 43	950043	Retaining Ring	1
22	B607ZZ	Ball Bearing	1	44	P013	Pin	1